

Reach 1

Issues: Appears to be historically straightened; channel is overwide with bare banks. Significant bare overbank areas due to disc golf usage. High clay content of soils helps reduce bank movement.

Constraints: Restoration must be compatible with disc golf course; need for bridge crossings. Narrow valley and low slope limit meandering potential. Deep shade limits vegetation options.




Figure 1

PLYMOUTH CREEK STUDY REACH 1
 Plymouth Creek Feasibility Study
 Bassett Creek Watershed
 Management Commission