

***Appendix B***  
***2008 Site Photos***



**Stream bank erosion and existing vegetation at Site 5.**



**Stream bank erosion and existing vegetation at Site 8.**





**Stormsewer outlet and bank erosion at Site 14.**



**Stream bank erosion and existing vegetation at Site 15.**